

# INDIGENOUS MONITOR OVERVIEW REPORT

Month: November 2023 Indigenous Monitor days on-site: 26

Project Region: BC Interior Kilometre Posts (KPs) monitored:

Spread 5A KP 806–974

### Indigenous Monitors on the Trans Mountain Expansion Project - Overview

The Trans Mountain Expansion Project (the Project or TMEP) has retained Indigenous Monitors as integrated members of its construction Environmental Inspection team. Indigenous Monitors work with Environmental Inspectors to monitor compliance with mitigation measures to minimize impacts to traditional resource use and cultural/heritage sites during construction. Indigenous Monitors have a strategic role in providing traditional knowledge directly and pragmatically to construction oversight practices and bring an Indigenous lens to daily environmental inspection activities.

This Overview Report provides highlights of the Indigenous Monitors' day-to-day work and key mitigation measures observed by the Monitors related to Project construction in the BC Interior Region. The purpose of this report is to provide an update on Indigenous Monitor activity to Indigenous groups.

During this reporting period, key activities in the BC Interior Region involving Indigenous Monitors took place from KP 806 to 974 in Spread 5A and included monitoring environmental features, dewatering activities, pipe installation and ditching. The Project Construction Progress Report (Condition 106) for November 2023, which reports environmental events and deficiencies in Tables 4 and 5 respectively, is found <a href="https://example.com/here.">here.</a>

The Project has a process for sharing information related to potential Traditional Land Use (TLU) and Heritage Resource chance finds during construction. The <u>Protecting TLU and Cultural Heritage Resources Fact Sheet (link here)</u> provides an overview of the chance find communication process. Applicable Indigenous groups are notified and engaged directly on potential chance finds.

For more information: email info@transmountain.com or call 1.866.514.6700.



#### **Environmental Features**

Environmental features that occur on or adjacent to the construction footprint are staked and flagged by Resource Specialist crews prior to commencing construction. This may include rare plants and rare ecological communities, wildlife species of concern, archaeological features, TLU sites and any other sensitive environmental or cultural features. The features are clearly marked so they may be avoided and/or protected during construction.

The Indigenous Monitors conducted inspections in areas of known environmental features to ensure flagging and staking of buffer zones are the correct distances. During the inspection, Indigenous Monitors identified a section of fencing that required maintenance and a damaged sign. Both corrective actions were brought to the attention of the environmental inspection team, which led to the items being repaired immediately. No further concerns were identified at this location.



Fencing installed at an environmental feature near KP 856 at Jacko Lake.



Signage confirmed at KP 855.

### **Dewatering Management**

During construction activity, water that accumulates within the Project area from precipitation or groundwater seepage is visually assessed prior to being pumped to areas approved by the Trans Mountain Environmental Inspector.

This water is discharged through a filtration device and into a well-vegetated area. From there, it will slowly infiltrate into local soils.

The Indigenous Monitors inspected the pump-off of water near KP 854. They observed water coming out of the filtration bag free of sediment. The release site was noted as well vegetated and the filtration bag was clean. The surface water pump-off mitigation measures were followed and verified. No concerns were identified.



Filtration bag and dewatering location for Pad 4.

Filtration bag setup at Pad 4 near KP 854.

## TRANSMOUNTAIN

### **Pipe Installation**

Topsoil stripping, pipe installation and backfill activities continued on Spread 5A. When removing soil in construction areas, required mitigation includes segregation of topsoil from root zone material, proper storage to reduce potential erosion, effective labelling and signage, and inspection of soil piles to ensure they are within the survey limits of the right-of-way and no soil has gone outside these limits.

The Indigenous Monitors noted mitigations for the topsoil piles to reduce erosion potential, including grading and identifying drainage pathways to reduce ponding. The Indigenous Monitors observed sand and subsoil being backfilled over the pipe prior to topsoil being replaced and ensured backfill activities were confined to the construction right-of-way. Construction activities were noted as confined to the construction right-of-way. No issues or potential chance finds were identified.



Pipe installation and trench backfill activities at KP 961.



Pipe installation and trench backfill at KP 961.

### Jacko Lake Excavation Activities

Near Jacko Lake, crews conducted excavation activities for the alternate construction method approved in September 2023. Near KP 853, the Indigenous Monitor met with the construction crew to discuss ditching and excavation of a 1.3-km trench. The inspection included monitoring the workmanship and safety of the crew on-site, trenching, soil stability and monitoring the perimeter of exclusion fencing and open trench for wildlife. Soil stripping activities were monitored to ensure activities stayed within the construction boundaries. Environmental features were monitored for continued avoidance, appropriate signage and buffers. No concerns were identified.



Ditching activities at KP 850.



Ditching activities at KP 853.



### **Indigenous Monitor Request Dashboard**

Indigenous Monitors are provided with daily on-site field support from Environmental Inspectors and office support from Indigenous Monitor Coordinators. Indigenous Monitors can also make specific support requests or submit questions through their daily report. Examples include but are not limited to requests for Project reports, input from an environmental resource specialist or on-site support from an Elder or other cultural knowledge holder. Monthly requests and their completion status are noted below.

Status	Rolling Total and Type of Requests				
	Project Reports/Documents	Environmental Resource Specialists	Elder/Cultural Knowledge Holder	Other	Total
Total	6	1	8	0	15
Fulfilled	6	1	8	-	15
Outstanding	-	-	-	-	-

This report has been reviewed by the active Indigenous Monitor(s)

