

INDIGENOUS MONITOR OVERVIEW REPORT

Month: February 2021

Indigenous Monitor days on-site: 0

**Project Region: North Thompson
(Spread 3/4a and Spread 4b)**

Kilometre Posts (KPs) N/A

Indigenous Monitors on the Trans Mountain Expansion Project – Overview

The Trans Mountain Expansion Project (the Project) has retained Indigenous Monitors as integrated members of its construction Environmental Inspection team. Indigenous Monitors work with Environmental Inspectors to monitor compliance with mitigation measures to minimize impacts to traditional resource use and cultural/heritage sites during construction. Indigenous Monitors have a strategic role in providing traditional knowledge directly and pragmatically to construction oversight practices and bring an Indigenous lens to daily environmental inspection activities.

This Overview Report provides highlights of the Indigenous Monitors' day-to-day work and key mitigation measures observed by the Monitors related to Project construction in the North Thompson region. The purpose of this report is to provide an update on Indigenous Monitor activity to Indigenous groups.

During this reporting period, Project activities in the North Thompson Region were on hold for a Project-wide safety shutdown. The Project Construction Progress Report (Condition 106) for February 2021, which reports environmental events and deficiencies in Tables 4 and 5 respectively, is found [here](#).

For more information: email info@transmountain.com or call 1.866.514.6700.

Trans Mountain COVID-19 – Our Response

Trans Mountain is actively monitoring the COVID-19 situation with the help of federal, provincial and local agencies. Trans Mountain's top priority remains the health and safety of its workforce, their families and our communities. Trans Mountain and its construction contractors are working diligently together to adhere to all advice and direction from government and health officials, while ensuring the safe uninterrupted operation of the Trans Mountain Pipeline and the continued, safe construction of the Expansion Project. Measures being undertaken at construction sites include: temperature screening; following physical distancing guidelines, staggering work shifts and breaks; eliminating or minimizing in-person meetings; enhancing cleaning and sanitizing; and ensuring workers' orientation includes COVID 19 expectations, awareness and prevention.

For more information: transmountain.com/covid19

Indigenous Monitor Request Dashboard

Indigenous Monitors are provided with daily on-site field support from Environmental Inspectors and office support from Indigenous Monitor Coordinators. Indigenous Monitors can also make specific support requests or submit questions through their daily report. Examples include but are not limited to: request for Project reports, input from an environmental resource specialist or on-site support from an Elder or other cultural knowledge holder. Monthly requests and their completion status are noted below.

Status	Rolling Total and Type of Requests				
	Project Reports/Documents	Environmental Resource Specialists	Elder/Cultural Knowledge Holder	Other	Total
Total	0	0	0	0	0
Fulfilled	-	-	-	-	-
Outstanding	-	-	-	-	-

This report has been reviewed by the active Indigenous Monitor(s)

CONTACT US:
Trans Mountain

✉ info@transmountain.com
☎ 1.866.514.6700
💻 transmountain.com



@TransMtn



youtube.com/transmtn



PO Box 81018
Burnaby, BC V5H 3B0

