

## INDIGENOUS MONITOR OVERVIEW REPORT

---

**Month: January 2021**

**Indigenous Monitor days on-site: 0**

**Project Region: Yellowhead (Spread 2)**

**Kilometre Posts (KPs) monitored:  
139–325**

### **Indigenous Monitors on the Trans Mountain Expansion Project – Overview**

The Trans Mountain Expansion Project (the Project) has retained Indigenous Monitors as integrated members of its construction Environmental Inspection team. Indigenous Monitors work with Environmental Inspectors to monitor compliance with mitigation measures to minimize impacts to traditional resource use and cultural/heritage impacts during construction. Indigenous Monitors have a strategic role in providing traditional knowledge directly and pragmatically to construction oversight practices and bring an Indigenous lens to daily environmental inspection activities.

This Overview Report provides highlights of the Indigenous Monitors' day-to-day work and key mitigation measures observed by the Monitors related to Project construction in the Yellowhead region. The purpose of this report is to provide an update on Indigenous Monitor activity to Indigenous groups.

During this reporting period, Project activities in the Yellowhead Region were on hold for a safety shutdown. The Project Construction Progress Report (Condition 106) for January 2021, which reports environmental events and deficiencies in Tables 4 and 5 respectively, is found [here](#).

**For more information: email [info@transmountain.com](mailto:info@transmountain.com) or call 1.866.514.6700.**

### **Trans Mountain COVID-19 – Our Response**

Trans Mountain is actively monitoring the COVID-19 situation with the help of federal, provincial and local agencies. Trans Mountain's top priority remains the health and safety of its workforce, their families and our communities. Trans Mountain and its construction contractors are working diligently together to adhere to all advice and direction from government and health officials, while ensuring the safe uninterrupted operation of the Trans Mountain Pipeline and the continued, safe construction of the Expansion Project. Measures being undertaken at construction sites include: following physical distancing guidelines, staggering work shifts and breaks; eliminating or minimizing in-person meetings; and enhancing cleaning and sanitizing; and ensuring workers orientation includes COVID 19 expectations, awareness and prevention.

**For more information: [transmountain.com/covid19](https://transmountain.com/covid19)**

## Indigenous Monitor Request Dashboard

Indigenous Monitors are provided daily on-site field support from Environmental Inspectors and office support from Indigenous Monitor Coordinators. Indigenous Monitors can also make specific support requests or submit questions through their daily report. Examples include but are not limited to: request for Project reports, input from an environmental resource specialist or on-site support from an Elder or other cultural knowledge holder. Monthly requests and their completion status are noted below.

Status	Total Number and Type of Requests				
	Project Reports/Documents	Environmental Resource Specialists	Elder/Cultural Knowledge Holder	Other	Total
Total	3	1	2	0	6
Fulfilled	3	1	2	-	6
Outstanding	-	-	-	-	-

This report has been reviewed by the active Indigenous Monitor(s)

### CONTACT US: Trans Mountain

✉ [info@transmountain.com](mailto:info@transmountain.com)  
☎ 1.866.514.6700  
💻 [transmountain.com](http://transmountain.com)

🐦 [@TransMtn](https://twitter.com/TransMtn)

📺 [youtube.com/transmtn](https://youtube.com/transmtn)



PO Box 81018  
Burnaby, BC V5H 3B0

